

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-3288
Inspection Date: 2026-09-09
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1240HRS.

Access road- No concerns at the time of inspection.

Lease environment- No vegetation on lease. Standing water at north-east area of lease. No erosion sediment or water runoff concerns at this time.

Lease Equipment: C-c45-D : Well appears active. ESD appears open. Barricades in place. Signage in place. Bypass locked and secure. Surface casing vent flow test- Minor Flow detected from glove test (glove partially filled in 1 min). Meter building entry test- No alarms on personal monitor. No concerns at time of inspection.

C-b45-D : Well appears active. ESD appears open. Barricades in place. Signage in place. Bypass locked and secure. Surface casing vent flow test- Flow detected from glove test (glove partially filled in 1 min). Bubble test performed from 1310 to 1320 Hours- No bubbles observed. Meter building entry test- No alarms on personal monitor. No concerns at time of inspection.

C-a45-D : Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- No Flow detected from glove test. Observed bucket hanging off Surface casing vent and discolored ground around base of vent. Minor staining on ground under valve, no active leak observed (See attached). Meter building entry test- No alarms on personal monitor. No concerns at time of inspection.

C-45-D : Well appears active. ESD appears open. Barricades in place. Signage in place. Bypass locked and secure. Surface casing vent flow test- Minor Flow detected from glove test (glove partially filled in 1 min).

Main meter building entry test- No alarms on personal monitor. Needle valve on flow line (tag description Well Outlet High Press) missing cap (see attached). No other concerns at the time of inspection.

Separator building entry test- No alarms on personal monitor. Active dripping from threaded connection (tag description Raw gas Sep High Level) on separator (see attached). No other concerns at the time of inspection.

Tanks and pump on site- No concerns at time of inspection.

Pig Station- No concerns at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100077941

Well ID: 29130

Well Name: TOURMALINE HZ N AITKEN C- 045-D/094-H-04

Location: NTS: C- 045-D/094-H-04

Permit: 100078055

Well ID: 29259

Well Name: TOURMALINE HZ N AITKEN C-A045-D/094-H-04

Location: NTS: C-A045-D/094-H-04

Permit: 100080023

Well ID: 30192

Well Name: TOURMALINE HZ N AITKEN C-B045-D/094-H-04

Location: NTS: C-B045-D/094-H-04

Permit: 100102969

Well ID: 33874

Well Name: TOURMALINE HZ AITKEN CREEK NORTH C-C045-D/094-H-04

Location: NTS: C-C045-D/094-H-04

Permit: 100077941

Facility ID: 00025892

Facility Name: TOURMALINE AITKEN CREEK NORTH C-045-D/094-H-04 001

Facility Type: Well Facility

Location: NTS: C- 045-D/094-H-04

Permit: 100078055

Facility ID: 00025923

Facility Name: TOURMALINE NORTHERNMONTNEY C-045-D/094-H-04 002

Facility Type: Well Facility

Location: NTS: C- 045-D/094-H-04



Inspection Number: 2026-3288
Inspection Date: 2026-09-09

Letter ID: L2604663
Letter Date: 2026-09-10

Authorized by BCER