

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.

Inspection: 2026-3289

Inspection Date: 2026-09-03

Inspection Outcome: Inspected

Inspection Comment:

WA# 711 Sept. 3, 2026: 13:27 on site.

Wellhead: SCVA ball valve handle was found in the open position; client is monitoring/reporting SCVF to standards. Wellhead flowlines are connected with all well valve handles are chained and locked.

KERMIT last reported gas production date: 2025-03

Signage is compliant to standards.

Well Facility: Suspended Status - Out of Service, Flare stack out of service.

Storage: all storage tanks (3) on site have SDS labels posted and tanks are grounded (Out of Service).

Flowline: flowline is blinded at pipeline (Suspended Status). Pig barrel safety chain is installed.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100000913

Well ID: 00711

Well Name: PETRONAS ET AL BEG A- 021-F/094-G-01

Location: NTS: A- 021-F/094-G-01

Permit: 100000913

Facility ID: 00018442

Facility Name: PETRONAS BEG A-021-F/094-G-01 001

Facility Type: Well Facility

Location: NTS: A- 021-F/094-G-01

Authorized by BCER



Inspection Number: 2026-3289
Inspection Date: 2026-09-03

Letter ID: L2604665
Letter Date: 2026-09-10