

Inspection Report

Permit Holder: Tourmaline Oil Corp.

Inspection: 2026-3290

Inspection Date: 2026-09-09

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1345HRS

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. Rig mats being stored at Southeast corner of lease (See attached). No erosion sediment or water runoff concerns.

Lease Equipment: C-c65-D : Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- not able to complete due to active pressure test being performed on vent (See attached). Meter building entry test- No alarms on personal monitor. No concerns at time of inspection.

C-b65-D: Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- Minor Flow detected from glove test (glove partially filled in approx. 1 min). Meter building entry test- No alarms on personal monitor. No concerns at time of inspection.

C-a65-D: Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- Minor Flow detected from glove test (glove partially filled in approx. 1 min). Meter building entry test- No alarms on personal monitor. No concerns at time of inspection.

C-65-D: Well appears active. ESD appears open. Barricades in place. Signage in place. Surface casing vent flow test- Minor Flow detected from glove test (glove partially filled in approx. 1 min). Meter building entry test- No alarms on personal monitor. No concerns at time of inspection.

Chemical tanks and pump on site- No concerns at time of inspection.

Separator Building entry test- No alarms on personal monitor. No concerns at the time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100103315
Well ID: 36126
Well Name: TOURMALINE HZ AITKEN CREEK NORTH C- 065-D/094-H-04
Location: NTS: C- 065-D/094-H-04

Permit: 100103315
Well ID: 36127
Well Name: TOURMALINE HZ AITKEN CREEK NORTH C-A065-D/094-H-04
Location: NTS: C-A065-D/094-H-04

Permit: 100103315
Well ID: 36128
Well Name: TOURMALINE HZ AITKEN CREEK NORTH C-B065-D/094-H-04
Location: NTS: C-B065-D/094-H-04

Permit: 100103315
Well ID: 36129
Well Name: TOURMALINE HZ AITKEN CREEK NORTH C-C065-D/094-H-04
Location: NTS: C-C065-D/094-H-04

Permit: 100115900
Facility ID: 00027610
Facility Name: TOURMALINE AITKEN CREEK C-065-D/094-H-04 001
Facility Type: Well Facility
Location: NTS: C- 065-D/094-H-04

Authorized by BCER