

## Inspection Report

Permit Holder: Yoho Resources Inc.

Inspection: 2026-3295

Inspection Date: 2026-09-10

Inspection Outcome: Inspected

### Inspection Comment:

- \* Travel to YOHO HZ INGA O01-19-087-23, sign in site orientation.
- \* Meet with site supervisors discuss operations and review documents.
- \* conduct site inspection and discuss with supervisors.
- \* no concerns upon completing this inspection.
- \* sign out return to Dawson Creek.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100118746

Well ID: 50078

Well Name: YOHO HZ INGA O01-19-087-23

Location: DLS: O01-19-087-23

---

Authorized by BCER