

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.

Inspection: 2026-3302

Inspection Date: 2026-09-11

Inspection Outcome: Inspected

Inspection Comment:

This inspection is a follow up to the level 1 incident of a produced water spill (2026-0243) at location d-97-G/ 94-B-08. The BCER inspector and Environmental Response Specialist attended the site on Friday Sept 11, 2026. Thanks to the on-site Petronas Operator for answering our questions about this leak from the root cause to clean up efforts. The inspection has the facility as inspected, however, that is just a reference for the follow up on the produced water spill and the facility was not inspected as per the usual inspection criteria for a facility.

The BCER Spill Response Specialist will follow up with their Petronas contacts for any further information requests.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100075850

Facility ID: 00007884

Facility Name: PETRONAS ALTARES D-097-G/094-B-08 001

Facility Type: Compressor Dehydrator

Location: NTS: D- 097-G/094-B-08

Authorized by BCER