

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3337
Inspection Date: 2026-09-17
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

COMMENTS:

- pipeline valves closed at time of inspection. No chain and lock on wellhead valves. Flowline is not disconnected. Well shows production as recent as July 2026.
- the planks that the chemical tank is sitting on are rotten and the stand is sinking into the ground. The tank is on a bit of a lean.
- lease, access and location signage is compliant.
- No SCVF
- location signage has both symbols. Well data shows no H2S present in gas stream, therefore, there should not be a sour gas symbol on the signage if data is correct.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100008686
Well ID: 05951
Well Name: CNRL EAGLE 06-30-084-17
Location: DLS: 06-30-084-17

Permit: 100028738
Pipeline Project ID: 000009351
Segment IDs (Location): 1 (From DLS: 06-30-084-17 To DLS: 05-25-084-18)

Authorized by BCER



Inspection Number: 2026-3337
Inspection Date: 2026-09-17

Letter ID: L2604740
Letter Date: 2026-09-18