

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3339

Inspection Date: 2026-09-17

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-Compressor station appears to be inactive. There are some blind flanges and some disconnected equipment. There is no well at this location. No flare at flarestack.

-lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100010856

Facility ID: 00000449

Facility Name: CNRL CECILLAKE 15-24-084-18 001

Facility Type: Battery Site

Location: DLS: 15-24-084-18

Permit: 100023052

Facility ID: 00000127

Facility Name: CNRL CECILLAKE 15-24-084-18 002

Facility Type: Satellite Battery

Location: DLS: 15-24-084-18

Permit: 100006517

Pipeline Project ID: 000002705

Segment IDs (Location): 5 (From DLS: 15-24-084-18 To DLS: 06-14-084-18)

Permit: 100022744

Pipeline Project ID: 000007702

Segment IDs (Location): 1 (From DLS: 15-24-084-18 To DLS: 16-23-084-18)

Authorized by BCER



Inspection Number: 2026-3339
Inspection Date: 2026-09-17

Letter ID: L2604742
Letter Date: 2026-09-18