

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3341

Inspection Date: 2026-09-17

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-electric pumpjack inactive at time of inspection. Pumpjack has anti-vibration shut down.

-No chain and lock on wellhead valves. No flowline disconnect. Well shows production as recent as July 2026.

-No SCVF

-lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100012210

Well ID: 07502

Well Name: CNRL UNIT EAGLE 09-25-084-18

Location: DLS: 09-25-084-18

Permit: 100012637

Facility ID: 00000850

Facility Name: CNRL EAGLE 09-25-084-18 001

Facility Type: Battery Site

Location: DLS: 09-25-084-18

Authorized by BCER