

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3342

Inspection Date: 2026-09-17

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-electric pumpjack inactive at time of inspection. No SCVF. No chain and lock on wellhead valves. No flowline disconnect. Well shows production as recent as July 2026. No AV/SD; not required.

-lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100008628

Well ID: 05903

Well Name: CNRL EAGLE 08-25-084-18

Location: DLS: 08-25-084-18

Permit: 100008685

Pipeline Project ID: 000003868

Segment IDs (Location): 3 (From DLS: 08-25-084-18 To DLS: 16-23-084-18)

Authorized by BCER