

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3343

Inspection Date: 2026-09-17

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-abandoned well. Looks to be a piping stub 2 feet high where wellhead would have been, sticking up out of the ground. Signage marking the spot looks to read project #5406.

-lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100008579

Well ID: 05867

Well Name: CNRL EAGLE 15-25-084-18

Location: DLS: 15-25-084-18

Authorized by BCER