

## Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3344

Inspection Date: 2026-09-17

Inspection Outcome: Inspected

### Inspection Comment:

#### COMMENTS:

-wellhead valves chained and locked. Flowline is disconnected from the wellhead.

No SCVF

-some vegetation starting to grow at the wellhead.

-lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100009384

Well ID: 06398

Well Name: CNRL EAGLE 11-25-084-18

Location: DLS: 11-25-084-18

Permit: 100013436

Pipeline Project ID: 000005406

Segment IDs (Location): 1 (From DLS: 11-25-084-18 To DLS: 15-25-084-18)

---

Authorized by BCER