

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3353
Inspection Date: 2026-09-22
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1515HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Well appears active. No barricades in place (Limited risk due to isolated location). Signage hidden behind vegetation at entrance (no signage on wellhead). Wellhead and flowline covered in insulated wrap. Surface casing vent flow test- Flow detected from glove test (Glove filled in 1 min).

Performed bubble test from 1517 to 1527- No observed bubbles. Meter building entry test- H2S detected on personal monitor. did not complete meter run inspection due to H2S detected.

Chemical tanks and pump on site- No concerns at time of inspection.

Pig Station- No concerns at time of inspection.

Note: Various drums filled with unknown substance stored around lease (See attached).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100054950
Well ID: 21387
Well Name: CNRL BEG A- 035-B/094-G-01
Location: NTS: A- 035-B/094-G-01

Permit: 100054950
Facility ID: 00022196
Facility Name: CNRL BEG A-035-B/094-G-01 001
Facility Type: Well Facility
Location: NTS: A- 035-B/094-G-01

Authorized by BCER