

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3356
Inspection Date: 2026-09-23
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) and secondary containment and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100039919
Well ID: 16668
Well Name: OVV ECOG HZ NOEL C- 081-C/093-P-08
Location: NTS: C- 081-C/093-P-08

Permit: 100039921
Well ID: 16732
Well Name: OVV ECOG HZ NOEL A- 092-C/093-P-08
Location: NTS: A- 092-C/093-P-08

Permit: 100045620
Well ID: 18910
Well Name: OVV ECOG HZ NOEL D- 082-C/093-P-08
Location: NTS: D- 082-C/093-P-08

Permit: 100039919
Facility ID: 00020352
Facility Name: OVV DEEPBASIN C-081-C/093-P-08 001
Facility Type: Well Facility
Location: NTS: C- 081-C/093-P-08

Permit: 100039921
Facility ID: 00020368
Facility Name: OVV DEEPBASIN A-092-C/093-P-08 001
Facility Type: Well Facility
Location: NTS: A- 092-C/093-P-08



Inspection Number: 2026-3356
Inspection Date: 2026-09-23

Letter ID: L2604776
Letter Date: 2026-09-24

Authorized by BCER