

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3360
Inspection Date: 2026-09-23
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100076532
Well ID: 28468
Well Name: OVV CRP ET AL HZ NOEL B- 015-H/093-P-07
Location: NTS: B- 015-H/093-P-07

Permit: 100076872
Well ID: 28711
Well Name: OVV CRP ET AL HZ NOEL B-A015-H/093-P-07
Location: NTS: B-A015-H/093-P-07

Permit: 100076532
Facility ID: 00025672
Facility Name: OVV DEEPBASIN B-015-H/093-P-07 001
Facility Type: Well Facility
Location: NTS: B- 015-H/093-P-07

Permit: 100076872
Facility ID: 00025764
Facility Name: OVV DEEPBASIN B-015-H/093-P-07 002
Facility Type: Well Facility
Location: NTS: B- 015-H/093-P-07

Authorized by BCER