

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3366
Inspection Date: 2026-09-24
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100060284
Well ID: 22909
Well Name: OVV ECOG HZ SWAN A-A032-H/093-P-09
Location: NTS: A-A032-H/093-P-09

Permit: 100060285
Well ID: 22910
Well Name: OVV ECOG HZ SWAN A-B032-H/093-P-09
Location: NTS: A-B032-H/093-P-09

Permit: 100060286
Well ID: 22911
Well Name: OVV ECOG HZ SWAN A-C032-H/093-P-09
Location: NTS: A-C032-H/093-P-09

Permit: 100060284
Facility ID: 00022857
Facility Name: OVV HERITAGE A-032-H/093-P-09 001
Facility Type: Well Facility
Location: NTS: A- 032-H/093-P-09

Permit: 100060285
Facility ID: 00022858
Facility Name: OVV HERITAGE A-032-H/093-P-09 002
Facility Type: Well Facility
Location: NTS: A- 032-H/093-P-09

Permit: 100060286
Facility ID: 00022859
Facility Name: OVV HERITAGE A-032-H/093-P-09 003
Facility Type: Well Facility
Location: NTS: A- 032-H/093-P-09

Authorized by BCER