

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.

Inspection: 2026-3369

Inspection Date: 2026-09-18

Inspection Outcome: Inspected

Inspection Comment:

I met the Petronas Operator on location who was conducting pipeline pigging operations. The site had minimal equipment such as a well head, meter run suitcases, chemical tank and a short pipeline riser.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100050809

Well ID: 20009

Well Name: PETRONAS JULIENNE A- 077-A/094-G-02

Location: NTS: A- 077-A/094-G-02

Permit: 100050809

Facility ID: 00021498

Facility Name: PETRONAS JULIENNECREEK A-077-A/094-G-02 001

Facility Type: Well Facility

Location: NTS: A- 077-A/094-G-02

Permit: 100083573

Road Number: 03869

Segment IDs (Location): 001 (From NTS: D- 057-A/094-G-02 To NTS: A- 077-A/094-G-02)

Authorized by BCER