

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3372

Inspection Date: 2026-09-22

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1045HRS.

Access road- No concerns at the time of inspection.

Lease environment- No vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Well appears active. ESD appears open. No barricades in place (Limited risk due to isolated location). Signage in place. Insulated wrap on wellhead. Surface casing vent flow test- No Flow detected from glove test.

Meter building entry test- No alarms on personal monitor. Calibration tags appear up to date. odors in building, no alarm on personal monitor. No concerns at time of inspection.

Chemical tanks and pump on site- No concerns at time of inspection

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100038767

Well ID: 16506

Well Name: CNRL BEG C-A026-I/094-B-16

Location: NTS: C-A026-I/094-B-16

Authorized by BCER