

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3377
Inspection Date: 2026-09-22
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1235HRS.

Access road-No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Well appears active. ESD appears open. No barricades in place (Limited risk due to isolated location). Signage in place. Surface casing vent flow test- Flow detected from glove test (Partially filled in 2 min). Meter building entry test- No alarms on personal monitor. Calibration tags up to date. No concerns at time of inspection.

Pig barrel safety chain is not attached to PAV (see attached).

Chemical tanks and pump on site- No concerns at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100038243
Well ID: 16301
Well Name: CNRL BEG B- 001-B/094-G-01
Location: NTS: B- 001-B/094-G-01

Authorized by BCER