

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3378

Inspection Date: 2026-09-22

Inspection Outcome: Inspected

Inspection Comment:

Proximity to Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1249HRS.

Access road- No concerns at the time of inspection.

Lease environment- Moderate overgrown vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- Flow detected from glove test (glove partially filled in 1 min).

Building entry test- No alarms on personal monitor. Building out of service.

Flare- Appears inactive.

Pig Station- No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100016306

Well ID: 08881

Well Name: CNRL HIGHWAY C- 091-J/094-B-16

Location: NTS: C- 091-J/094-B-16

Authorized by BCER