

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-3380
Inspection Date: 2026-09-22
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1409HRS.

Access road- No concerns at the time of inspection.

Lease environment- Various vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. Barricades in place. Signage (faded) in place at well (see attached). Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Upper master valve and wing valve handles not chained, locked and secure or removed (see attached).
Surface casing vent flow test- Flow detected from glove test (glove partially filled in 2 min).

Building entry test- No alarms on personal monitor. Building out of service.

Tanks and secondary containment on site- containment approx. half full (see attached). No concerns at time of inspection.

Pig Station- Deactivated. No concerns at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100071837
Well ID: 26517
Well Name: PETRONAS JEDNEY B- 046-H/094-G-01
Location: NTS: B- 046-H/094-G-01

Permit: 100071837
Facility ID: 00024730
Facility Name: PETRONAS JEDNEY B-046-H/094-G-01 001
Facility Type: Well Facility
Location: NTS: B- 046-H/094-G-01

Authorized by BCER