

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-3382
Inspection Date: 2026-09-22
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1443HRS.

Access road- No concerns at the time of inspection.

Lease environment- Various vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended. Barricades in place. Signage at entrance, obstructed by overgrown vegetation (See attached). Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- Flow detected from glove test (glove partially filled in 2 min).

Building entry test- No alarms on personal monitor. Building out of service.

Pig Station- Out of service.

Tanks on site-Out of service.

Note; Various garbage and discarded equipment on site (see attached).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100072202
Well ID: 26634
Well Name: PETRONAS JEDNEY B- 056-H/094-G-01
Location: NTS: B- 056-H/094-G-01

Permit: 100072202
Facility ID: 00024783
Facility Name: PETRONAS JEDNEY B-056-H/094-G-01 001
Facility Type: Well Facility
Location: NTS: B- 056-H/094-G-01

Authorized by BCER