

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3388

Inspection Date: 2026-09-23

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1205HRS.

Access road- No concerns at the time of inspection.

Lease environment- Various vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Well appears active. Barricades in place. Signage in place.
Wellhead and flowline covered in insulated wrap. Surface casing vent flow test-
No Flow detected from glove test.

Meter building entry test- No alarms on personal monitor. Meter calibration tags appear up to date. No concerns at time of inspection.

Tanks on site-No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100001424

Well ID: 01095

Well Name: CNRL ET AL BEG D- 057-B/094-G-01

Location: NTS: D- 057-B/094-G-01

Authorized by BCER