

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3389

Inspection Date: 2026-09-23

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1218HRS.

Access road- No concerns at the time of inspection.

Lease environment- Various vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Well appears active. No barricades in place (Limited risk due to isolated location). Signage in place. Wellhead and flowline covered in insulated wrap. ESD appears open. Surface casing vent flow test-Flow detected from glove test (Glove filled in 1 minute.) Performed bubble test 1222 to 1232- No bubbles observed.

Meter building entry test- No alarms on personal monitor. Meter calibration tags appear up to date. No concerns at time of inspection.

Chemical tanks and pump on site- No concerns at time of inspection.

Tanks on site-No concerns at time of inspection.

Flare on site- Inactive. No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100022867

Well ID: 11489

Well Name: CNRL ET AL BEG D- 068-B/094-G-01

Location: NTS: D- 068-B/094-G-01

Authorized by BCER



Inspection Number: 2026-3389
Inspection Date: 2026-09-23

Letter ID: L2604832
Letter Date: 2026-09-28