

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.

Inspection: 2026-3390

Inspection Date: 2026-09-24

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1031HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead appears suspended at time of inspection. Current status "Active". Internal records indicate well has not produced since Sept 2026. No barricades in place (Limited risk due to isolated location). Signage in place. Flow line positive isolation from wellhead (spec blind). Surface casing vent flow test- No Flow detected from glove test.

Meter building entry test- No alarms on personal monitor. Meter calibration tags appear up to date. No concerns at time of inspection.

Tanks on site- Out of service. No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100048806

Well ID: 19620

Well Name: PETRONAS TOWN B- 031-C/094-G-01

Location: NTS: B- 031-C/094-G-01

Permit: 100048806

Facility ID: 00021284

Facility Name: PETRONAS BEGWEST B-031-C/094-G-01 001

Facility Type: Well Facility

Location: NTS: B- 031-C/094-G-01



Inspection Number: 2026-3390
Inspection Date: 2026-09-24

Letter ID: L2604835
Letter Date: 2026-09-28

Authorized by BCER