

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3427

Inspection Date: 2026-09-23

Inspection Outcome: Inspected

Inspection Comment:

This is a multi well pad. The foil covered bubble wrap on the stainless steel tubing at the tank farm is badly degraded to the point where it is falling off and blowing around the lease. Please remove, repair or replace. The chemical tanks are in good shape and complaint in their set up. The meter runs and orifice plate service, calibration and inspections are up to date as required. No concerns other than the degraded bubble wrap.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100070129

Well ID: 25895

Well Name: CNRL HZ BLAIR C-A055-F/094-B-16

Location: NTS: C-A055-F/094-B-16

Permit: 100073220

Well ID: 26913

Well Name: CNRL HZ BLAIR B- 055-F/094-B-16

Location: NTS: B- 055-F/094-B-16

Permit: 100081619

Well ID: 30971

Well Name: CNRL HZ BLAIR B-A055-F/094-B-16

Location: NTS: B-A055-F/094-B-16

Permit: 100081620

Well ID: 30972

Well Name: CNRL HZ BLAIR B-B055-F/094-B-16

Location: NTS: B-B055-F/094-B-16

Permit: 100081621

Well ID: 30973

Well Name: CNRL HZ BLAIR B-C055-F/094-B-16

Location: NTS: B-C055-F/094-B-16

Permit: 100081622
Well ID: 30974
Well Name: CNRL HZ BLAIR B-D055-F/094-B-16
Location: NTS: B-D055-F/094-B-16

Permit: 100084197
Facility ID: 00018341
Facility Name: CNRL BLAIR B-055-F/094-B-16 001
Facility Type: Well Facility
Location: NTS: B- 055-F/094-B-16

Authorized by BCER