

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-3431
Inspection Date: 2026-09-29
Inspection Outcome: Inspected

Inspection Comment:

Proximity to Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1400HRS.

Access road- No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100048951
Well ID: 19687
Well Name: TOURMALINE CONROY B- 059-C/094-H-12
Location: NTS: B- 059-C/094-H-12

Permit: 100048951
Facility ID: 00021325
Facility Name: TOURMALINE CONROYCREEK B-059-C/094-H-12 001
Facility Type: Well Facility
Location: NTS: B- 059-C/094-H-12

Authorized by BCER