

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-3432
Inspection Date: 2026-09-29
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1405HRS.

Access road- No concerns at the time of inspection.

Lease environment- No vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- B-69-C: Well appears active. Internal records indicate last production February 2026. ESD appears open. No barricades in place (Higher risk due to multiple wells on site). Signage in place at wells. Surface casing vent flow test- No Flow detected from glove test. Meter building entry test- No alarms on personal monitor. Meter calibration tags appear up to date. No concerns at time of inspection.

B-a69-C: Well appears active. Internal records indicate last production February 2026. ESD appears open. No barricades in place (Higher risk due to multiple wells on site). Signage in place at wells. Surface casing vent flow test- No Flow detected from glove test. Meter building entry test- No alarms on personal monitor. Meter calibration tags appear up to date. No concerns at time of inspection.

B-b69-C: Well appears active. Internal records indicate last production February 2026. ESD appears open. No barricades in place (Higher risk due to multiple wells on site). Signage in place at wells. Surface casing vent flow test- No Flow detected from glove test. Meter building entry test- No alarms on personal monitor. Meter calibration tags appear up to date. Unknown fluid coming from handle on needle valve attached to flowline (See attached). No other concerns at time of inspection.

Tanks on site-No concerns at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100064902
Well ID: 24178
Well Name: TOURMALINE CONROY B- 069-C/094-H-12
Location: NTS: B- 069-C/094-H-12

Permit: 100064963
Well ID: 24260
Well Name: TOURMALINE CONROY B-A069-C/094-H-12
Location: NTS: B-A069-C/094-H-12

Permit: 100064964
Well ID: 24261
Well Name: TOURMALINE CONROY B-B069-C/094-H-12
Location: NTS: B-B069-C/094-H-12

Permit: 100064902
Facility ID: 00023536
Facility Name: TOURMALINE CONROYCREEK B-069-C/094-H-12 001
Facility Type: Well Facility
Location: NTS: B- 069-C/094-H-12

Permit: 100064963
Facility ID: 00023585
Facility Name: TOURMALINE CONROYCREEK B-069-C/094-H-12 002
Facility Type: Well Facility
Location: NTS: B- 069-C/094-H-12

Permit: 100064964
Facility ID: 00023586
Facility Name: TOURMALINE CONROYCREEK B-069-C/094-H-12 003
Facility Type: Well Facility
Location: NTS: B- 069-C/094-H-12

Authorized by BCER