

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-3433
Inspection Date: 2026-09-29
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1427HRS.

Access road- No concerns at the time of inspection.

Lease environment- Various vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- C-70-C: Wellhead Suspended. Barricades in place. Signage in place on well. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Upper master and flow line valve handle not chained, locked & secure or removed (See attached). Needle valve on wellhead missing plug (See attached). Surface casing vent flow test- No Flow detected from glove test.

C-a70-C: Wellhead Suspended. Barricades in place. No signage in place on well (See attached). Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Flow line valve handle not chained, locked & secure or removed (See attached). Surface casing vent flow test- Minor Flow detected from glove test (Partially filled in 2 min).

C-b70-C: Wellhead Suspended. Barricades in place. No signage in place on well (See attached). Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- Minor Flow detected from glove test (Partially filled in 2 min).

Note: various uneven ground, potholes, and minor pits, around location where buildings and pilings appear to have been removed (See attached).

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100048950
Well ID: 19686
Well Name: TOURMALINE CONROY C- 070-C/094-H-12
Location: NTS: C- 070-C/094-H-12

Permit: 100064842
Well ID: 24158
Well Name: TOURMALINE CONROY C-A070-C/094-H-12
Location: NTS: C-A070-C/094-H-12

Permit: 100064925
Well ID: 24236
Well Name: TOURMALINE CONROY C-B070-C/094-H-12
Location: NTS: C-B070-C/094-H-12

Permit: 100048950
Facility ID: 00021324
Facility Name: TOURMALINE CONROYCREEK C-070-C/094-H-12 001
Facility Type: Well Facility
Location: NTS: C- 070-C/094-H-12

Permit: 100064842
Facility ID: 00023524
Facility Name: TOURMALINE CONROYCREEK C-070-C/094-H-12 003
Facility Type: Well Facility
Location: NTS: C- 070-C/094-H-12

Permit: 100064925
Facility ID: 00023572
Facility Name: TOURMALINE CONROYCREEK C-070-C/094-H-12 004
Facility Type: Well Facility
Location: NTS: C- 070-C/094-H-12

Authorized by BCER