

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-3442
Inspection Date: 2026-10-02
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1305HRS.

Access road- No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Wellhead Suspended. Internal records indicate status is listed as active but has not produced since February 2024. Barricades in place. Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- Unable to perform test due to hose attached.

Building entry test- No alarms on personal monitor. Building inactive.

Tanks and secondary containment on site-No concerns at time of inspection. Inactive.

Flare on site- Inactive

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100000958
Well ID: 00739
Well Name: PETRONAS ET AL BEG B-A099-B/094-G-01
Location: NTS: B-A099-B/094-G-01



Inspection Number: 2026-3442
Inspection Date: 2026-10-02

Letter ID: L2604929
Letter Date: 2026-10-05

Authorized by BCER