

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-3443
Inspection Date: 2026-10-02
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1243HRS.

Access road- Various ruts along road. No concerns at the time of inspection.

Lease environment- Various vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Wellhead appears suspended. Internal records indicate status as Active & well has not produced since June 2025. Barricades in place. Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected from glove test.

Building entry test- No alarms on personal monitor. Building Inactive.

Tanks and secondary containment on site-No concerns at time of inspection. Inactive.

Chemical tanks and pump on site- No concerns at time of inspection. Inactive

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100038824
Well ID: 16559
Well Name: PETRONAS BEG B-A088-B/094-G-01
Location: NTS: B-A088-B/094-G-01

Permit: 100038824
Facility ID: 00020320
Facility Name: PETRONAS BEG B-088-B/094-G-01 001
Facility Type: Well Facility
Location: NTS: B- 088-B/094-G-01

Authorized by BCER