

Inspection Report

Permit Holder: ARC Resources Ltd.

Inspection: 2026-3445

Inspection Date: 2026-10-02

Inspection Outcome: Inspected

Inspection Comment:

Inspection Summary

Site 09-08-080-14 was inspected at approximately 1050 hours. Weather conditions were sunny, with a temperature of 17°C.

Inspection Findings

- Access and signage: Signage was clear and legible.
- Site condition: The wellsite was clean, with no vegetation concerns noted.
- Wellheads: Bull plugs, SCV, locks, and leaks were checked. No SCV flow was detected. Critical valves were locked, with no concerns noted.
- Meter/separator buildings: Locks, leaks, caps, and vents were checked, with no concerns noted.
- Chemical tanks: Leaks, grounds, and caps were checked, with no concerns noted.
- Riser and pig stations: Chains and grounds were checked, with no concerns noted.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100071609

Well ID: 26514

Well Name: ARGRES DOE 09-08-080-14

Location: DLS: 09-08-080-14

Permit: 100080772

Well ID: 30623

Well Name: ARGRES HZ DOE A09-08-080-14

Location: DLS: A09-08-080-14

Permit: 100100091

Facility ID: 00026232

Facility Name: ARGRES DAWSON CREEK 09-08-080-14 001

Facility Type: Well Facility

Location: DLS: 09-08-080-14

Permit Holder: ARC Resources Ltd.



Inspection Number: 2026-3445
Inspection Date: 2026-10-02

Letter ID: L2604937
Letter Date: 2026-10-05

Authorized by BCER