

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-3456
Inspection Date: 2026-10-07
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1340HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Wellhead appears suspended at time of inspection. Internal records indicate status is active, last production on Sept 2025. No barricades in place (Limited risk due to isolated location). Signage in place at entrance. Valve Handles chained, locked and secure. Casing valve handles not chained, locked & secure or removed. Surface casing vent flow test-Flow detected (glove test results filled in 1 min). Bubble test performed from 1345 to 1355- No bubbles observed.

Building entry test- No alarms on personal monitor. Plug missing off fitting tagged "PL PPHH" (See attached).

Tanks on site-No concerns at time of inspection.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100055099
Well ID: 21383
Well Name: PETRONAS W BEG C- 062-C/094-G-01
Location: NTS: C- 062-C/094-G-01

Permit: 100055099
Facility ID: 00022195
Facility Name: PETRONAS BEGWEST C-062-C/094-G-01 001
Facility Type: Well Facility
Location: NTS: C- 062-C/094-G-01

Authorized by BCER