

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.

Inspection: 2026-3463

Inspection Date: 2026-10-07

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1431HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Wellhead appears suspended at time of inspection. Internal records indicate status is active, last production on Sept 2025. No barricades in place (Limited risk due to isolated location). Signage in place at entrance. ESD appears closed. Positive isolation maintained (flowline). Valve Handles chained, locked and secure. Casing valve handles not chained, locked & secure or removed. Surface casing vent flow test- no Flow detected.

Building entry test- No alarms on personal monitor. No concerns at time of inspection.

Tanks-No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100055561

Well ID: 21433

Well Name: PETRONAS W BEG A- 073-C/094-G-01

Location: NTS: A- 073-C/094-G-01

Permit: 100055561

Facility ID: 00022220

Facility Name: PETRONAS BEGWEST A-073-C/094-G-01 001

Facility Type: Well Facility

Location: NTS: A- 073-C/094-G-01



Inspection Number: 2026-3463
Inspection Date: 2026-10-07

Letter ID: L2604963
Letter Date: 2026-10-08

Authorized by BCER