

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.

Inspection: 2026-3467

Inspection Date: 2026-10-07

Inspection Outcome: Inspected

Inspection Comment:

Proximity to Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1515HRS.

Access road- No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Wellhead Suspended. No barricades in place (Limited risk due to isolated location). Signage in place at entrance. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure. Surface casing vent flow test- No Flow detected.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100048554

Well ID: 19591

Well Name: PETRONAS W BEG D- 074-C/094-G-01

Location: NTS: D- 074-C/094-G-01

Permit: 100048554

Facility ID: 00021273

Facility Name: PETRONAS BEGWEST D-074-C/094-G-01 001

Facility Type: Well Facility

Location: NTS: D- 074-C/094-G-01

Authorized by BCER