

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.

Inspection: 2026-3468

Inspection Date: 2026-10-07

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1500HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment- Wellhead appears suspended at time of inspection. Internal records indicate status is active, last production on August 2025. No barricades in place (Limited risk due to isolated location). Signage in place at entrance. ESD appears closed. Positive isolation maintained (flowline).
Flowline propped up by peice of wood (See attached). Valve Handles chained, locked and secure. Casing valve handles not chained, locked & secure or removed.
Surface casing vent flow test-No Flow detected.

Building entry test-Unable to perform meter run inspection due to handles being zip tied shut (See attached).

Tanks and secondary containment on site-No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100052568

Well ID: 20843

Well Name: PETRONAS W BEG A- 074-C/094-G-01

Location: NTS: A- 074-C/094-G-01

Permit: 100052568

Facility ID: 00021944

Facility Name: PETRONAS BEGWEST A-074-C/094-G-01 002

Facility Type: Well Facility

Location: NTS: A- 074-C/094-G-01



Inspection Number: 2026-3468
Inspection Date: 2026-10-07

Letter ID: L2604968
Letter Date: 2026-10-08

Authorized by BCER