

## Inspection Report

Permit Holder: Canlin Energy Corporation

Inspection: 2026-3473

Inspection Date: 2026-10-02

Inspection Outcome: Inspected

### Inspection Comment:

#### Inspection Summary

Site 09-25-081-16 was inspected at approximately 1300 hours. Weather conditions were sunny, with a temperature of 17°C.

#### Inspection Findings

- Access and signage: Signage was clear and legible. Two gates with chains, cattle at large. The culvert at or near the corner remains damaged at both ends, half full of debris/mud.
- Site condition: The wellsite was clean, with some vegetation on site (below around Flare base and knockout).
- Wellheads: Bull plugs, SCV, locks, and leaks were checked. No SCV flow was detected. Critical valves were locked, with no concerns noted.
- Meter/separator buildings: Locks, leaks, caps, and vents were checked, line heater marked out of service, with no concerns noted.
- Chemical tanks: Leaks, grounds, and caps were checked, with no concerns noted.
- Riser and pig stations: Chains and grounds were checked, with no concerns noted.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100024344

Well ID: 12123

Well Name: CANLIN ET AL PARKLAND 09-25-081-16

Location: DLS: 09-25-081-16

Permit: 100024344

Facility ID: 00019496

Facility Name: CANLIN PARKLAND 09-25-081-16 001

Facility Type: Well Facility

Location: DLS: 09-25-081-16

---

Authorized by BCER



Inspection Number: 2026-3473  
Inspection Date: 2026-10-02

Letter ID: L2604974  
Letter Date: 2026-10-09