

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-3474
Inspection Date: 2026-10-02
Inspection Outcome: Inspected

Inspection Comment:

Inspection Summary

Site 08-24-081-16 was inspected at approximately 0000 hours. Weather conditions were sunny/windy, with a temperature of 14°C.

Inspection Findings

- Access and signage: Signage was at the wellhead only. Gate open on this day.
- Site condition: The wellsite was clean, with vegetation at the wellhead.
- Wellheads: Bull plugs, SCV, locks, and leaks were checked. No SCV flow was detected. Critical valves were locked, with no concerns noted. Signage on wellhead.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100025873
Well ID: 12779
Well Name: CANLIN ET AL PARKLAND 08-24-081-16
Location: DLS: 08-24-081-16

Permit: 100025873
Facility ID: 00019594
Facility Name: CANLIN PARKLAND 08-24-081-16 001
Facility Type: Well Facility
Location: DLS: 08-24-081-16

Permit Holder: Canlin Energy Corporation

Authorized by BCER