

Inspection Report

Permit Holder: ARC Resources Ltd.

Inspection: 2026-3475

Inspection Date: 2026-10-02

Inspection Outcome: Inspected

Inspection Comment:

Inspection Summary

Site 08 & 09-03-081-16 were inspected at approximately 1341 hours. Weather conditions were sunny, with a temperature of 17°C.

Inspection Findings

- Access and signage: Signage was clear and legible.
- Site condition: The wellsite was clean, with no vegetation concerns noted. On site roads are scoured. see photos.
- Wellheads: Bull plugs, SCV, locks, and leaks were checked. No SCV flow was detected. Critical valves were locked, with no concerns noted.
- Meter/separator buildings: Locks, leaks, caps, and vents were checked, facility 08-03 beside same numbered well as signage 09-03 - see photo.
- Chemical tanks: Leaks, grounds, and caps were checked, with no concerns noted.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100055213

Well ID: 21472

Well Name: ARCRES PARKLAND 08-03-081-16

Location: DLS: 08-03-081-16

Permit: 100060850

Well ID: 23101

Well Name: ARCRES ET AL PARKLAND 09-03-081-16

Location: DLS: 09-03-081-16

Permit: 100061231

Well ID: 23219

Well Name: ARCRES ET AL HZ PARKLAND A09-03-081-16

Location: DLS: A09-03-081-16

Permit: 100055213
Facility ID: 00022243
Facility Name: ARCRES HERITAGE 08-03-081-16 001
Facility Type: Well Facility
Location: DLS: 08-03-081-16

Permit Holder: ARC Resources Ltd.

Authorized by BCER