

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.

Inspection: 2026-3481

Inspection Date: 2026-10-13

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

10-35-84-17:

-wellhead only, valves chained and locked. No SCVF

-pipeline riser onsite with guarding around it.

A10-35-84-17:

-abandoned well with piping stub sticking up out of ground.

-lease, access and location signage is compliant.

-gate at beginning of lease road but not locked.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100004192

Well ID: 03123

Well Name: PETRONAS ET AL W FLATROCK 10-35-084-17

Location: DLS: 10-35-084-17

Permit: 100015088

Well ID: 08455

Well Name: PETRONAS ET AL HZ W FLATROCK A10-35-084-17

Location: DLS: A10-35-084-17

Permit: 100004192

Facility ID: 00018636

Facility Name: PETRONAS FLATROCKWEST 10-35-084-17 001

Facility Type: Well Facility

Location: DLS: 10-35-084-17

Permit: 100010700
Facility ID: 00000218
Facility Name: PETRONAS CECILLAKE 10-35-084-17 002
Facility Type: Compressor Station
Location: DLS: 10-35-084-17

Permit: 100015414
Facility ID: 00001400
Facility Name: PETRONAS FLATROCK 10-35-084-17 003
Facility Type: Battery Site
Location: DLS: 10-35-084-17

Authorized by BCER