

## Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3483

Inspection Date: 2026-10-13

Inspection Outcome: Inspected

### Inspection Comment:

#### COMMENTS:

-wellhead valves chained and locked. Flowline is disconnected from the wellhead.

No SCVF

-Compressor, dehy, separator not in service. 4-400bbl tanks inside tank farm and one lying down on lease.

-Lease, access and location signage is compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100014774

Well ID: 08317

Well Name: CNRL ET AL HZ W FLATROCK 05-02-085-17

Location: DLS: 05-02-085-17

Permit: 100014774

Facility ID: 00019115

Facility Name: CNRL FLATROCKWEST 05-02-085-17 001

Facility Type: Well Facility

Location: DLS: 05-02-085-17

Permit: 100016032

Facility ID: 00001350

Facility Name: CNRL FLATROCK 05-02-085-17 002

Facility Type: Processing Battery

Location: DLS: 05-02-085-17

Permit: 100015740

Pipeline Project ID: 000005971

Segment IDs (Location): 3 (From DLS: 05-02-085-17 To DLS: 10-35-084-17), 4 (From DLS: 05-02-085-17 To DLS: 10-35-084-17)



Inspection Number: 2026-3483  
Inspection Date: 2026-10-13

Letter ID: L2604994  
Letter Date: 2026-10-14

---

Authorized by BCER