

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3484

Inspection Date: 2026-10-13

Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-wellhead only. Only two (2) of the five (5) wellhead valves are chained and locked. As per the Guidelines, all valves must be locked closed besides the SCV valve on a surface suspended well. Flowline is disconnected from the wellhead.

-there is guarding around the wellhead in a field. The access road is overgrown and there is a Petronas (?) location sign at the access, but a CNRL location sign on the wellhead.

-no SCVF

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100011453

Well ID: 07167

Well Name: CNRL ET AL W FLATROCK 09-03-085-17

Location: DLS: 09-03-085-17

Permit: 100015740

Pipeline Project ID: 000005971

Segment IDs (Location): 5 (From DLS: 09-03-085-17 To DLS: 05-02-085-17)

Authorized by BCER