

Inspection Report

Permit Holder: Canadian Natural Resources Limited

Inspection: 2026-3510

Inspection Date: 2026-10-14

Inspection Outcome: Inspected

Inspection Comment:

The test separator, tank farm, pipeline header are compliant in their set up. All wells were active at the time of inspection. The b-b and and b-c surface casing vents are plumbing into plastic tanks that don't have much , if anything in them. The b-a surface casing vent is gurgling and should be retested as the last test was just after completions with a 10 min bubble test. Please send the results to BCER engineering as per your usual submissions.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100112587

Well ID: 41669

Well Name: CNRL HZ KOBES B-C062-C/094-B-16

Location: NTS: B-C062-C/094-B-16

Permit: 100112587

Well ID: 41670

Well Name: CNRL HZ KOBES B-B062-C/094-B-16

Location: NTS: B-B062-C/094-B-16

Permit: 100112587

Well ID: 41671

Well Name: CNRL HZ KOBES B-A062-C/094-B-16

Location: NTS: B-A062-C/094-B-16

Permit: 100112587

Well ID: 41672

Well Name: CNRL HZ KOBES B- 062-C/094-B-16

Location: NTS: B- 062-C/094-B-16

Permit: 100118095

Facility ID: 00027960

Facility Name: CNRL DAIBER B-062-C/094-B-16 001

Facility Type: Well Facility

Location: NTS: B- 062-C/094-B-16



Inspection Number: 2026-3510
Inspection Date: 2026-10-14

Letter ID: L2605044
Letter Date: 2026-10-20

Authorized by BCER