

Inspection Report

Permit Holder: ARC Resources Ltd.
Inspection: 2026-3531
Inspection Date: 2026-10-22
Inspection Outcome: Inspected

Inspection Comment:

Inspection Overview

Site 11-20-079-14 was inspected at approximately 0000 hours. Conditions were overcast with a temperature of 6°C.

Inspection Results

- Access and signage: Signage removed, access other sites.
- Site condition: Equipment removed and currently a cultivated field.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100028342
Well ID: 13660
Well Name: ARGRES DAWSON 11-20-079-14
Location: DLS: 11-20-079-14

Permit: 100028342
Facility ID: 00019739
Facility Name: ARGRES HERITAGE 11-20-079-14 001
Facility Type: Well Facility
Location: DLS: 11-20-079-14

Permit: 100042118
Pipeline Project ID: 000013101
Segment IDs (Location): 1 (From DLS: 05-20-079-14 To DLS: 11-20-079-14), 2 (From DLS: 11-20-079-14 To DLS: 05-20-079-14)

Permit Holder: ARC Resources Ltd.



Inspection Number: 2026-3531
Inspection Date: 2026-10-22

Letter ID: L2605070
Letter Date: 2026-10-23

Authorized by BCER