

Inspection Report

Permit Holder: Cenovus Energy Inc.
Inspection: 2026-3533
Inspection Date: 2026-10-22
Inspection Outcome: Inspected

Inspection Comment:

- * Travel to CVE ENERGY HZ CUTBANK B-A081-A/093-P-08. sign in, site orientation.
- * Meet with site supervisors.
- * Discuss operations, review documents
- * As this is the first Accumulator placement under the doghouse within 15m from well, discussed and reviewed associated documents and requirements going forward.
- * Conduct site inspection. discuss site inspection with supervisors.
- * sign out return to Dawson Creek.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100121681
Well ID: 57086
Well Name: CVE ENERGY HZ CUTBANK B-A081-A/093-P-08
Location: NTS: B-A081-A/093-P-08

Authorized by BCER