

Inspection Report

Permit Holder: Westcoast Energy GP Inc.

Inspection: 2026-3535

Inspection Date: 2026-10-15

Inspection Outcome: Inspected

Inspection Comment:

Inspection with the operator October 15, 2026.

The Azouzetta workspace AD 100119780, ancillary 246690. The workspace has been cleared and constructed to grade. The site has 2 access points, one is gated and the other is barricaded with cement blocks. Discussion with the operator, this site has two Authorizations and follow up is required to determine actual work division for the Sunrise Expansion Project and for Operations.

CS-2B compressor site instream works authorizations AD 100121893, CIAS 10541, Locations 1 & 2, work ongoing, culverts removed at the time of the inspection. Discussion with the operator on Site 743.01 signage stated, "NCD Fish Bearing" Operator is to provide stream assessment to confirm status as fish bearing or non-fish bearing on or before November 6, 2026. Discussion with the operator on relocation of the existing Tidewater pipeline. Operator is to notify the undersigned of start date for this work 2 days prior to start of construction.

2BL crossover site, AD 100121583, Road 07218, Seg 001, Road has been raised, road ditches are lined with rock (work ongoing), 2 cross drain culverts are still to be installed, CIAS 10733, WET-1486, location 2 permanently removed during road construction, location 1, NCD, site 89, permanent culvert installed with rock at upstream and downstream ends. Observed a small flow of sediment laden water flowing in road ditch to the culvert. Operator immediately installed ESC and initiated corrective measures. Work space, ancillary number 26674, active storage of soils, woody debris, stumps etc.

AD 100121795, STWU 6907, POD 001, Misinchinka River, Permit is active, but the site has not been set up and no water withdrawals to date.

3L crossover, AD 100122848, Road 7251, segment 001, utilizing existing road to where it meets the pipeline ROW. A partially matted travel lane has been built down the ROW to the crossover. The permitted road will be constructed at a later time. CIAS 10869, location 12, WC 145a.02, existing culvert. location 2, not disturbed at the time of the inspection. location 4, 7, & 8, WET 062, KP 13+180 to 13+280, matt crossing installed with ESC and amphibian area 251, KP 13+160 to 13+280, location 3, 5, & 6, Site 149, NCD, location 9 & 10, site 149.01, matt crossing with ESC. There were no concerns noted at the time of the inspection.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100121583
Road Number: 07218
Segment IDs (Location): 001 (From NTS: A- 069-F/093-O-02 To NTS: B- 079-F/093-O-02)

Permit: 100122848
Road Number: 07251
Segment IDs (Location): 001 (From NTS: A- 036-C/093-J-15 To NTS: C- 024-C/093-J-15)

Permit: 100119780
AACT Number: 00246690
Site Type: Workspace

Permit: 100121583
AACT Number: 00266762
Site Type: Workspace

Permit: 100121583
AACT Number: 00266763
Site Type: Workspace

Permit: 100121583
AACT Number: 00266764
Site Type: Workspace

Permit: 100121583
CIAS Number: 0010733
Location ID (Crossing Type): 1 (Culvert), 2 (Culvert)

Permit: 100121893
CIAS Number: 0010541
Location ID (Crossing Type): 1 (Culvert), 2 (Culvert)

Permit: 100122848
CIAS Number: 0010869
Location ID (Crossing Type): 2 (Culvert), 3 (Culvert), 4 (Matting), 5 (Culvert), 6 (Culvert), 7 (Culvert), 8 (Matting), 9 (Culvert), 10 (Culvert), 12 (Culvert)

Permit: 100121795
STWU Number: 0006907
POD Number (POD Type): 001 (Stream/River)

Permit: 100119780

Permit: 100119780
Permit Condition:
Any temporary access must be constructed and maintained in a manner that provides for proper surface drainage, prevents pooling on the surface, and maintains slope integrity.

Permit: 100119780
Permit Condition:
Construction activities must not result in rutting, compaction or erosion of soils that cannot be reasonably rehabilitated to similar levels of soil productivity that existed on the activity area prior to the construction activities taking place.

Permit: 100121583

Permit: 100121795

Permit: 100121893

Permit: 100122848

Permit Holder: Westcoast Energy GP Inc.

Authorized by BCER