

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.

Inspection: 2026-3543

Inspection Date: 2026-10-22

Inspection Outcome: Inspected

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1540HRS.

Access road- No concerns at the time of inspection.

Lease environment- Limited vegetation on lease. Ruts created by water runoff at north end of lease & minor erosion off lease. No Observed sediment running off lease (See attached).

Lease Equipment- Wellhead appears suspended at time of inspection. Internal records indicate status is active, last production on Sept 2025. Barricades in place. Signage in place at entrance. ESD appears closed. No positive isolation maintained. Valve Handles chained, locked and secure. Casing valve handles not chained, locked & secure or removed. Surface casing vent flow test- No Flow detected.

Building entry test- No alarms on personal monitor. Meter calibration tags unclear (See attached) No other concerns at time of inspection.

Tanks on site-No concerns at time of inspection.

Flare on site- isolated from flowline with spec blinds. No concerns at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100044203

Well ID: 18350

Well Name: PETRONAS TOWN D- 038-C/094-G-01

Location: NTS: D- 038-C/094-G-01

Permit: 100044203
Facility ID: 00020843
Facility Name: PETRONAS TOWN D-038-C/094-G-01 001
Facility Type: Well Facility
Location: NTS: D- 038-C/094-G-01

Authorized by BCER