

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-3559
Inspection Date: 2026-10-27
Inspection Outcome: Inspected

Inspection Comment:

Inspection Overview

Site 13-22-079-17 was inspected at approximately 1230 hours. Conditions were overcast/ windy, with a temperature of 1°C.

Inspection Results

Access and signage: Signage was clear and easy to read.

Site condition: The wellsite was clean, with no vegetation-related concerns. A couple spots damp and rutted.

Wellheads: Bull plugs, SCV, locks, and potential leaks were inspected. No SCV flow was detected, and all critical valves were locked. No concerns were identified.

Meter/separator buildings: Locks, leaks, caps, and vents were inspected. No concerns were identified.

Chemical tanks: Tanks were checked for leaks and inspected for proper grounding and secure caps. No concerns were identified.

Riser and pig stations: Chains and grounding were inspected. No concerns were identified.

Associated pipelines: Vegetation cover along the pipelines was well established.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100073013
Well ID: 27053
Well Name: OVV HZ SUNRISE 13-22-079-17
Location: DLS: 13-22-079-17

Permit: 100073014
Well ID: 27056
Well Name: OVV HZ SUNRISE A13-22-079-17
Location: DLS: A13-22-079-17

Permit: 100073015
Well ID: 27057
Well Name: OVV CRP HZ SUNRISE B13-22-079-17
Location: DLS: B13-22-079-17

Permit: 100073016
Well ID: 27058
Well Name: OVV CRP HZ SUNRISE C13-22-079-17
Location: DLS: C13-22-079-17

Permit: 100073017
Well ID: 27059
Well Name: OVV CRP HZ SUNRISE D13-22-079-17
Location: DLS: D13-22-079-17

Permit: 100073018
Well ID: 27060
Well Name: OVV CRP HZ SUNRISE E13-22-079-17
Location: DLS: E13-22-079-17

Permit: 100073013
Facility ID: 00024973
Facility Name: OVV HERITAGE 13-22-079-17 001
Facility Type: Well Facility
Location: DLS: 13-22-079-17

Permit: 100073014
Facility ID: 00024974
Facility Name: OVV SUNRISE 13-22-079-17 002
Facility Type: Well Facility
Location: DLS: 13-22-079-17

Permit: 100073015
Facility ID: 00024975
Facility Name: OVV HERITAGE 13-22-079-17 003
Facility Type: Well Facility
Location: DLS: 13-22-079-17

Permit: 100073016
Facility ID: 00024976
Facility Name: OVV HERITAGE 13-22-079-17 004
Facility Type: Well Facility
Location: DLS: 13-22-079-17

Permit: 100073017
Facility ID: 00024977
Facility Name: OVV HERITAGE 13-22-079-17 005
Facility Type: Well Facility
Location: DLS: 13-22-079-17

Permit: 100073018
Facility ID: 00024978
Facility Name: OVV HERITAGE 13-22-079-17 006
Facility Type: Well Facility
Location: DLS: 13-22-079-17

Permit: 100118691
Pipeline Project ID: 000026437
Segment IDs (Location): 1 (From DLS: 04-22-079-17 To DLS: 05-27-079-17)

Permit: 100107591
Road Number: 05258
Segment IDs (Location): 001 (From DLS: 12-22-079-17 To DLS: 13-22-079-17)

Permit Holder: Ovintiv Canada ULC

Authorized by BCER