Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3568
Inspection Date: 2026-10-30
Inspection Outcome: Inspected

Inspection Comment:
WA# 20012 - Oct. 30, 2026: 9:56 hrs. on site.

Wellhead: SCVA ball valve is found in the open [position, no LEL gas measured (Altair-5x), and no flow observed.

Kermit last reported gas production rate: 2026-09 is in "Active Status".

Signage is compliant to standards.

Well Facility: Cata-dyne regulator vent lines present. Service records inspected on site: meter calibration date: 2022 and orifice plate service record: 2025.

Chemical Storage: double wall tank (1x) on metal stand, grounded, and SDS labels posted.

Flowline: active flowline is connected to wellhead, well building, and not disconnected (isolated) to pipeline. Pig barrel chain attached to PAV.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100049979
Well ID: 20012
Well Name: CNRL HZ HELMET C- 002-A/094-P-08
Location: NTS: C- 002-A/094-P-08

Permit: 100049979
Facility ID: 00021500
Facility Name: CNRL HELMET C-002-A/094-P-08 001
Facility Type: Well Facility
Location: NTS: C- 002-A/094-P-08

Authorized by BCER