Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3569
Inspection Date: 2026-10-30
Inspection Outcome: Inspected

Inspection Comment:
WA# 18005 - Oct. 30, 2026: 10:06 hrs. on site. BCER/CNRL joint field Inspection.

Wellhead: SCVA ball valve handle is found in the open position, no LEL gas was measured (Altair-5x), and no flow was observed.

Kermit last reported gas production rate: 2026-09 is in "Active Status".

Signage is compliant to standards.

Well Facility: Cata-dyne regulator vent lines present. Service records inspected on site: meter calibration date: 2025 and orifice plate service record: 2026.

Storage: double wall tank (1x) on metal stand, grounded, and SDS labels posted.

Flowline: active flowline is connected to wellhead, well building, and not disconnected (isolated) to pipeline. Pig barrel chain attached to PAV (2x).

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100043730
Well ID: 18005
Well Name: CNRL HZ HELMET C- 004-A/094-P-08
Location: NTS: C- 004-A/094-P-08

Permit: 100043730
Facility ID: 00020735
Facility Name: CNRL HELMET C-004-A/094-P-08 001
Facility Type: Well Facility
Location: NTS: C- 004-A/094-P-08

Permit: 100044669
Pipeline Project ID: 000013739
Segment IDs (Location): 2 (From NTS: C- 064-I/094-P-01 To NTS: C- 004-A/094-P-08)

Permit: 100046785
Pipeline Project ID: 000014393
Segment IDs (Location): 2 (From NTS: C- 004-A/094-P-08 To NTS: C- 006-A/094-P-08)

_____

Authorized by BCER