Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-3576
Inspection Date: 2026-10-30
Inspection Outcome: Inspected

Inspection Comment:
WA# 18837 and 18838 (A) - Oct. 30, 2026: 12:11 hrs. on site. BCER/CNRL joint inspection.

Wellheads (2x): SCVA ball valve handle is found in the open position, no LEL gas was measured (Altair-5x), and no flow was observed.

Kermit last reported gas production rate (2x): 2026-09 = “Active Status” production.

Signage is compliant to standards.

Well Facilities: Cata-dyne regulator vent lines present. Service records inspected on site: meter calibration date: 2023 and orifice plate service record: 2026. Note: A minor amount of LEL gas leak measured in well building WA# 18838 (A), source unknown: CNRL: is in the process of investigating and resolving the LEL gas detected.

Chemical Storage: double wall tanks (4x) on metal stands, bull plug installed, grounded and SDS labels present.

Flowline: flowlines are connected to the wellheads, well building, and pipeline. Pig barrel chain is attached to PAV. CNRL serviced/replaced a missing bull plug on the flowline injection port at the time of the inspection

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100045603
Well ID: 18837
Well Name: CNRL HZ HELMET D- 081-J/094-P-01
Location: NTS: D- 081-J/094-P-01

Permit: 100045604
Well ID: 18838
Well Name: CNRL HZ HELMET D-A081-J/094-P-01
Location: NTS: D-A081-J/094-P-01

Permit: 100045603
Facility ID: 00020977
Facility Name: CNRL HELMET D-081-J/094-P-01 001
Facility Type: Well Facility
Location: NTS: D- 081-J/094-P-01

_____

Authorized by BCER